Web Site: www.slouxvalleyenergy.com

Telephone: 605-534-3535 • Toll-Free: 1-800-234-1960 Office Fax: 605-256-1693 • Dispatch Fax: 605-256-1690

April 10, 2006

TECEVEU

APR 1 3 2006

Patty Van Gerpen, Executive Director South Dakota Public Utilities Commission 500 East Capitol Pierre, SD 57501

SOUTH DAKOTA PUBLIC UTILITIES COMMISSION

Dear Ms. Van Gerpen:

Enclosed for filing please find an original copy of an executed "Service Territory Exception Agreement" between Sioux Valley-Southwestern Electric cooperative, dba Sioux Valley Energy and Northern States Power Company dba Xcel Energy.

This agreement between the two parties seeks a modification to our existing service territories allowing each party to better serve Fraternal Order of Police (FOP). Pursuant to South Dakota Statute 49-34A-55 this Territory Exception will eliminate the duplication of facilities. Xcel Energy has an existing pole across the road where the Fraternal Order of Police (FOP) would like to have the light installed. This exception would also allow Xcel Energy to provide adequate electric service to this consumer which ultimately will provide efficient and economical use and development of our electric system.

This consent on the part of Sioux Valley Energy is limited to the said service to the FOP light. The light is located along the north side of SD Hwy 38 in the northwest quarter of section 28 of Split Rock Township 101N R48W in Minnehaha County, SD and will automatically terminate upon removal or abandonment of such service.

The accompanying drawing, Exhibit A to the Agreement, provides additional information. Sioux Valley Energy respectfully requests the South Dakota Utilities commission's consideration and an order approving this agreement.

Sincerely,

George Colombe

Director of Engineering and Operations

Heorge Colombe

Enc

A Touchstone Energy Cooperative

## SERVICE TERRITORY EXCEPTION AGREEMENT BETWEEN XCEL ENERGY AND SIOUX VALLEY ENERGY

Sioux Valley Southwestern Electric Cooperative, Inc. doing business as Sioux Valley Energy (SVE) and Northern States Power Company doing business as Xcel Energy jointly agree to have Xcel Energy provide electric service to a Fraternal Order of Police light. The light is located on the north side of South Dakota State Highway 38 near Riverview Road east of Sioux Falls, SD. A drawing of the service site is attached to this agreement as exhibit A.

Sioux Valley Energy and Xcel Energy have concluded that, in this instance, the customer's interests will be best service by receiving service from Xcel Energy and have agreed to this exception to the existing territorial agreement.

We also agree that each such instance where territory boundaries become a factor will be dealt with on an individual basis.

This consent on the part of Sioux Valley Energy is limited to the said service to the FOPA light located along the north side of SD Hwy 38 in the northwest quarter of section 28 of Split Rock Township 101N R48W in Minnehaha County, SD and will automatically terminate upon removal or abandonment of such service.


This exception is not to be construed as having any impact upon or indicating a desire to change the service areas assigned by the South Dakota Public Utilities Commission.

XCEL ENERGY

The Parties agree to jointly submit these agreed upon changes to the South Dakota Public Utilities Commission for approval.

SIOUX VALLEY SOUTHWESTERN

ELECTRIC COOPERATIVE	
BY Jafe General Manager	BY ACUUCA Manager, Government & Regulatory Affairs
DATE <u>4-4-06</u>	DATE March 23,2006







Not to Scale PIELD CHECKED BY Eric Pauli

CTY. SIOUX Falls

ADB. 9700 E Hwy 42

Design No. 162797

Vork Order /
MAP. M828N

FDR. MHA71-4 13.8 kv

SY XING PERSUT /
DATE 1-31-05

DESIGNER Eric Pauli

LOCATES

ONE CALL X YES NO

ONE CALL X YES NO

ONE CALL DA SECT.

101N RANGE 48W

+ STREET 48IS Ave

DESC. Install oh and

LXMIT.

nightwatch on new 40' pole.

This map is a tool to usual employees in the performance of their jobs. Your personal earliest is provided for by using safety procides, procedures and equipment as described in safety training programs, manuals and SPARs.

Exhibit